

we deliver
you discover



SERVICE PLAN FOR CS500-SERIES SCREW CAP RECAPPER

A standard PM service plan for maintaining your equipment.



STANDARD PM SERVICE PLAN

Ship unit to workshop

- One (1) scheduled PM inspection
- Performance test
- Thorough cleaning and lubrication of machine axis, spindles and guidings
- Functionality testing of machine axis, motor, slip couplings, bits and o-rings
- Inspection of fuses, guides, o-rings, springs, power cords and plugs (adjustment, replacement or repair of these parts done as necessary)
- Exclusions: all repair parts

KEEP YOUR
EQUIPMENT IN
TOP SHAPE!